INVOICE

ORD # 98-03-324

INVOICE # 972557

MAR 1 8 1998

03/16/98 09:47:45

PHONE (317) 290-1471

you again in the future.

TERMS Net 30 Days

INVOICE <u>Milbank Manufacturing Company</u> REMIT <u>See Below</u> TO 1400 E. Havens

P.O. Box 754

Kokomo, IN 46903-0754

ATTEN Ronda S. Yeakley ATTEN Accounts Receivable

WORK ID Effluent Water Composite P.O. # 207777 Thank you for your business. We look forward to working with

REPORT Milbank Manufacturing Company

TO 1400 E. Havens P.O. Box 754 Kokomo, IN 46903-0754

ATTEN Ronda S. Yeakley

RECEIVED 03/11/98 CLIENT MILBANK MFG

REPORTED 03/13/98 PROJECT

	<u>1D</u>	CODE	DESCRIPTION	REMARK	PRICE	QTY	DISCOUN	r amount
TESTS		AG_IC	Silver, ICAPES			1		
		FE_IC	Iron, ICAPES			1		
		PB_IC	Lead, ICAPES			1		
		ZN_IC	Zinc, ICAPES		1000	1	(新生) 生	100 May 2016

QUOTED PRICE \$147.00 TOTAL INVOICE AMOUNT \$147.00

A Member of THE ASTBURY GROUP



## CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 98-03-324 Date: 03/13/98 09:16

Work ID: Effluent Water Composite

Date Received: 03/11/98
Date Completed: 03/12/98

Client Code: MILBANK\_MFG

## SAMPLE IDENTIFICATION

Sample Sample

Number Description

O1 Effluent Composite

Sample

Sample

Number Description

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only

to the items tested.

This report contains a total number of pages: 02

Certified By



Order # 98-03-324 03/13/98 09:16

TEST RESULTS BY SAMPLE

Page 2

Sample:	01AW	Effluent	Composite
---------	------	----------	-----------

Collected: 03/1	0/98	Category:	WATER
-----------------	------	-----------	-------

Test Description	Result	Limit	<u>Units</u>	Analyzed	By
Iron, ICAPES	0.392	0.010	mg/L	03/12/98	JAR
Lead, ICAPES	<0.040	0.040	mg/L	03/12/98	JAR
Silver, ICAPES	<0.010	0.010	mg/L	03/12/98	JAR
Zinc, ICAPES	2.460	0.010	mg/L	03/12/98	JAR





## ES aboratories

5933 West 71<sup>st</sup> Street \* Indianapolis, IN 46278 Phone (317) 290-1471 \* Fax (317) 290-1670

## CHAIN OF CUSTODY RECORD

基
32
19
6

Client Name:    Milbout MfG   Project No:   Project Name:			Name:	ESG Work Order #:	Total	Filtered (Y or N) Preserv. Code  Analyses  A = Acid B = Base											
Sample	r(s) Signati	ıre:	a	În		Number of	/	poster		/ /	/ /	/ /	/ /	/ /	/ /	/ /	B = Base C = Cool 4°
Stat.No	DATE	TIME	СОМР	GRAB	STATION LOCATION ID	Containers		Mor	$\angle$	$\angle$	$\angle$	$\angle$	$\angle$	$\angle$	$\angle$	Comments	
	3-10-95	30-220	×		Eff- Pit	(	/										
							ļ										······································
							ļ										
							ļ										
							<b> </b>		ļ			_	-				
<u> </u>							-					_	-	-			
				-			-				-	_		-			
	7.				<u> </u>		<del> </del>		<del>                                     </del>	-		-	-				
											<u> </u>		<u> </u>		-		
Relinquished By: Date / Time		5	Received By:		Date / Time   Additional Information:    Turn Around Time: Normal   Rush   Report Due:												
Relinquished By: Date / Time		Time	Received By:	Date / Time	ne Are samples suspected to be: Flammable Corrosive Toxic							Toxic					
					Were samples received intact and properl				rly pre	eserved? Yes	No 🗀						
Relinquished By: Date / Ti		Time	Received By:	Date / Time		Temp	. Blan	ık	°C								
longlague																	***************************************